

XYZ 2000

INSTRUCTION MANUAL



XYZ Machine Tools Ltd
Woodlands Business Park
Burlescombe, Tiverton
Devon, EX16 7LL
Tel: 01823 674200 Fax: 01823 674201

TABLE OF CONTENT

| | |
|--|-----|
| 1. SAFE INSTRUCTIONS | 1-2 |
| 2. SPECIFICATION | 3 |
| 3. TRANSPORTATION | 4-5 |
| 4. INSTALLATION | |
| 4-1 FLOOR PLAN | 6 |
| 4-2 FOUNDATION, POWER SUPPLY | 7 |
| 4-3 CLEANING | 8 |
| 4-4 INITIAL SETTING ANCILIARY EQUIPMENT | 9 |
| 5. PUTTING INTO SERVICE | |
| 5-1 CUTTING SPEED | 10 |
| 5-1A TABLE .1. RECOMMENDED CUTTING SPEED | 11 |
| 5-2 FEED SPEED | 12 |
| 5-2A ¹ RECOMMENDED FEED PER TOOTH FOR CUTTERS | 13 |
| 5-3 CUTTING DEPTH | 14 |
| 5-4 PROBLEM DIAGNOSTIC AND TROUBLESHOOTING OF MILLING | 15 |
| 6. OPERATION | |
| 6-1 HEAD CONTROLS | 16 |
| 6-2 OPERATING PANEL | 17 |
| 6-3 SWIVEL TURRET, MOVE RAM SLIDE | 18 |
| 6-4 SPINDLE SPEED, CHANG RANGE, FROM BACK GEAR TO DIRECT DRIVE | 19 |
| 6-5 SWIVEL BELT HOUSING, SPINDLE BRAKE, QUILL SENSITIVE HAND FEED | 20 |
| 6-6 FINE HAND FEED, AUTOMATIC FEED | 21 |
| 6-7A CLAMPING THE TABLE SADDLE SLIDE, CLAMPING THE SADDLE KNEE SLIDE | 22 |
| 6-7C CLAMPING THE KNEE COLUMN SLIDE | 23 |
| 6-8A GUARD FOR SAFE USE | 24 |
| 6-8B GUARD FOR SAFE USE | 25 |
| 6-9 POWER FEED FOR SAFE USE | 26 |
| 7. MAINTENANCE | |
| 7-1 TRANSPORTATION, INSTALLATION | 27 |
| 7-2 MOTOR REMOVAL | 28 |
| 7-3 COLLECT ALIGNING SCREW REPLACEMENT | 29 |
| 7-3A COLLECT ALIGNING SCREW REPLACEMENT | 30 |
| 7-4 BALANCE SPRING REPLACEMENT, FEED TRIP ADJUSTMENT | 31 |
| 7-5 QUILL REMOVAL | 32 |
| 7-6 ADJUSTMENT OF TABLE GIB, ADJUSTMENT OF SADDLE GIB | 33 |
| 7-7 ADJUSTMENT OF KNEE GIB | 34 |
| 7-8 BACKLASH ADJUSTMENT | 35 |
| 7-9 BACKLASH ADJUSTMENT | 36 |

IMPORTANT SAFETY NOTICE WARNING

The King Rich Milling Machine.

SAFE INSTALLATION

It is the customers responsibility to ensure the machine is installed in a safe operating position, with all service pipes and cables clear of the operation area so as not to cause a hazard. Access must be allowed for safe maintenance, swarf and oil disposal including safe stacking of machined and unmachined components.

MACHINE GUARDING

The Milling Machine is fitted with standard safety guards. In certain cases and tooling applications additional guarding may have to be provided by the user to ensure proper safety.

AUTHORISED PERSONAL AND TRAINING

Operating, service and maintenance engineers shall be authorised by the User Company, and properly trained in the use of the machine.

SAFE WORKING PRACTICES

Workholding devices, lifting equipment, tooling and their use shall be the responsibility of the user. It is the user's responsibility to protect against the hazards caused by swarf, leaking oil or coolant and their use.

Use of proprietary oil or coolant is the responsibility of the user. Special instructions from the suppliers concerning their use should be carefully read and understood before use.

To prevent bodily injury safe working practices should be employed when operating or servicing the machine.



IMPORTANT SAFETY NOTICE WARNING

The King RICH Milling Machine.

SAFE INSTALLATION

It is the customers responsibility to ensure the machine is installed in a safe operating position, with all service pipes and cables clear of the operation area so as not to cause a hazard. Access must be allowed for safe maintenance, swarf and oil disposal including safe stacking of machined and unmachined components.

MACHINE GUARDING

The Milling Machine is fitted with standard safety guards. In certain cases and tooling applications additional guarding may have to be provided by the user to ensure proper safety.

AUTHORISED PERSONAL AND TRAINING

Operating, service and maintenance engineers shall be authorised by the User Company, and properly trained in the use of the machine.

SAFE WORKING PRACTICES

Workholding devices, lifting equipment, tooling and their use shall be the responsibility of the user. It is the user's responsibility to protect against the hazards caused by swarf, leaking oil or coolant and their use.

Use of proprietary oil or coolant is the responsibility of the user. Special instructions from the suppliers concerning their use should be carefully read and understood before use.

To prevent bodily injury safe working practices should be employed when operating or servicing the machine.

IMPORTANT

SAFETY INFORMATION

To prevent serious bodily injury, you should observe the following basic safety precautions when installing, operating or servicing your milling machine.

1. Follow all instructions in the machine instructions manual.
2. Wear approved industrial safety glasses and safety shoes.
3. Do not wear gloves, long sleeves, long hair, rings, watches, jewelry or other loose items that could become caught in moving parts.
4. Keep all parts of your body away from moving parts (belts, cutters, gears, etc.)
5. Use proper point of operation safeguarding.

TABLE OF CONTENT

| | |
|--|--------|
| 8. LUBRICATION | |
| 8-1 VARIABLE SPEED DRIVE HEAD | 37 |
| 8-2 AUTO OIL-FEED ADJUSTMENT | 38 |
| 8-3 UP-DOWN OIL SYSTEM | 39 |
| 8-4 SADDLE OIL SYSTEM | 40 |
| 8-5 COOLANT OIL, SLIDE WAY OIL | 41 |
| 9. INSTRUCTION FOR DIAGRAM | |
| A. CAUTION | 42 |
| B. DISENGAGE FEED GEAR | |
| C. BRAKE | |
| D. SPEED SELECTION | |
| E. CAUTION | 43 |
| F. VARIABLE SPEED LIST | |
| G. LIST OF RECOMMENDED OILS OR EQUAL | 44 |
| H. PLEASE | |
| I. MACHINE NAMEPLATE | |
| J. DANGER | 45 |
| K. GENERAL DIAGRAM POSITION | 46 |
| ANNEX: | |
| A. PART DRAWING | |
| A1. VARIABLE HEAD DRAWING | 47-48 |
| A2. VERTICAL MILLING HEAD DRAWING | 49-50 |
| A3. LEFT-RIGHT DRAWINGS, UP-DOWN DRAWING | 51-52 |
| A4. FRONT-REAR DRAWING | 53-54 |
| B. CONTROL CIRCUIT | |
| B1. INSTALLATION DRAWING | 55-1-2 |
| B2. LAY OUT OF CONTROL PANEL | 56 |
| B3. LAY OUT OF ELECTRICAL CABINET | 57 |
| B4. CIRCUIT DIAGRAM | 58-1-5 |
| B5. ELECTRICAL PART LIST | 59-1-3 |
| C. NOISE TEST | 60 |
| D. IMPORTER ADDRESS | 61 |


1. SAFE INSTRUCTION

1. DON'T run your machine until you have read and understood the KING RICH operator and maintenance manuals.
2. DON'T run your machine until you have read and understood all machine and control key signs
3. DON'T run your machine for the first time without a qualified instructor. ASK your supervisor for help when you need it.
4. PROTECT your eyes. Wear safety glasses with side shields at all times.
5. DON'T get caught in moving parts. Remove watches, rings, jewelry, neckties, and loose-fitting clothes.
6. PROTECT your head. Wear a safety helmet when working near overhead hazards.
7. KEEP your hair away from moving parts.
8. PROTECT your feet. Always wear safety shoes with steel toes and oil-resistance soles.
9. Gloves are easily caught in moving parts. TAKE THEM OFF before you turn on the machine.
10. Loose objects can become flying projectiles. REMOVE all loose items(wrenches, chuck keys, rags, etc.) from machine before starting.
11. NEVER operate a machine tool after taking strong medication, using non-prescription drugs or consuming alcoholic beverages.
12. SAFEGUARD the cutting zone("point of operation"). Use standard, general purpose safeguard where possible. Use special safeguards when required.
13. Protect your hands. STOP the spindle completely BEFORE changing tools.
14. Protect your hands. STOP the spindle completely BEFORE you load or unload a workpiece.
15. Protect your hands, STOP the spindle completely BEFORE you clear away chips or oil. Use brush or chip scraper. NEVER use your hands.
16. Protect your hands. STOP the spindle completely BEFORE you adjust the workpiece, fixture or coolant nozzle.
17. Protect your hands. STOP the spindle completely BEFORE you take measurements.
18. Protect your hands. STOP the spindle completely BEFORE you open safeguard or covers. Never reach around a safeguard.
19. Protect your hands. STOP the machine BEFORE you change or adjust belts, pulleys or gears.
20. PROTECT your hands. Keep hands and arms clear of spindle start switch when changing tools.
21. PROTECT your eyes. Never use a compressed air hose to remove chips.

SAFE INSTRUCTION

22. KEEP work area well lighted. Ask for additional light if needed.
23. DON'T slip. Keep your work area clean and dry .Remove chips, oil and obstacles.
24. NEVER lean on your machine. Stand away when the machine is running.
25. DON'T get trapped. Avoid pinch points caused by motion of table and head.
26. PREVENT objects from flying loose. Securely clamp and locate workpiece. Use stop blocks where necessary. KEEP clamps clear of cutter path.
27. PREVENT cutter breakage. Use correct table feed and spindle speed for the job. Reduce feed and speed if you notice unusual noise or vibration.
28. PREVENT cutter breakage. Rotate spindle in clockwise direction for right-hand tools, counterclockwise for left-hand tools. Use the correct tool for the job.
29. PREVENT workpiece and cutter damage. Never start the machine when the cutter is in contact with the workpiece.
30. Dull and damaged tools break easily. Inspect tools and tool holders. Keep tools sharp. Keep tool overhang short.
31. Keep rotating cranks and handwheels well-lubricated and maintained. Do not remove safety springs.
32. Certain materials, such as magnesium, are highly flammable in dust and chip form. See your supervisor before working with these materials.
33. PREVENT fire. Keep flammable liquids and materials away from work area and hot chips.
34. PREVENT machine from moving unexpectedly. Disengage power feed when not being used(manual machines only)
35. PREVENT machine from moving unexpectedly. Always start machine in manual mode.
36. DON'T be used in a potentially explosive, dusty, atmosphere.
37. NON-METAL materials can not be used to work in this machine.
38. OPERATORS DON'T use gloves or necktie.
39. The machine must be grounded circuit, otherwise it will have electrical leakage conditions.

SPECIFICATION



| TYPE | KR-V2000 | | KR-V2000 | | | | | | |
|------------------------------|---------------------------------------|--------------------|---------------|--------------|--|--|--|--|--|
| SPECIFICATION | INCH SYSTEM | | METRIC SYSTEM | | | | | | |
| Table size | 10" × 48" | 10" × 50" | 254 × 1220mm | 254 × 1270mm | | | | | |
| Tee slots(3) | 5/8" | | 15.9mm | | | | | | |
| Longitudinal travel(× Axis) | 30" | 32" | 762mm | 812mm | | | | | |
| Cross travel | 16" | | 406mm | | | | | | |
| Knee vertical travel | 16" | | 406mm | | | | | | |
| Quill travel | 5" | | 127mm | | | | | | |
| Quill diameter | 4 1/8" | | 105mm | | | | | | |
| Quill feeds | .0015" .003" .006" | .038mm .076 .152mm | | | | | | | |
| Spindle motor | 3HP | | | | | | | | |
| Spindle speeds | Low:60-500 RPM High:500-4200RPM(60Hz) | | | | | | | | |
| Spindle taper | R8/ISO 30 | | | | | | | | |
| Ram travel | 17 3/4" | | 450mm | | | | | | |
| Spindle nose to top of table | 2"-18" | | 50-457mm | | | | | | |
| Overarm Swivel on turret | 360° | | | | | | | | |
| Head tilt front to back | 45°-0-45° | | | | | | | | |
| Head tilt left to right | 90°-0-90° | | | | | | | | |
| Max. throat depth | 24" | | 610mm | | | | | | |
| Max. table load | 770lbs | | 350kgs | | | | | | |
| Approx. net weight | 2750lbs | | 1250kgs | | | | | | |


3. TRANSPORTATION

HANDLING WEIGHT

Basic machine approximately 2750 lb(1250kg)

(A) METHOD 1


Insert 1" Whitworth eye bolt in tapped hole. Ensure bolt is fully secured before lifting. It is advisable to swivel head before lifting machine.



Sketch #1

(B) METHOD 2

Use rope sling as illustrated. Insert pads of soft cloth between rope and machined edges. It is advisable to tilt the head before lifting machine.




Sketch #2

3. TRANSPORTATION

(C) METHOD 3


Using lift truck to transfer the package as picture.



Sketch #3

4. INSTALLATION

4-1 FLOOR PLAN




Sketch #4

4. INSTALLATION

4-2A FOUNDATION

Ideally all milling machines should be bolted to a concrete foundation.


The KING RICH however should be placed on a solid level floor or antivibration pads to prevent any rocking movement.



Sketch #5

4-2B POWER SUPPLY

- Check the panel voltage against the main supply.
- Connect the supply to the isolator (diagram).
- Check for correct spindle rotation. (In the HIGH SPEED range the spindle should rotate clockwise when viewed from the top of the machine).



Sketch #6 ISOLATOR DIAGRAM

4. INSTALLATION

4-3 CLEANING

1. Remove rust preventative before moving any slideways.
2. The coating is best removed by using paraffin applied with a clean brush. When the coating has softened, remove with clean rags.
3. Oil or grease all lubrication points. Refer to the lubrication section of this manual (sketch #39).
4. Check all equipment against the delivery note. Any discrepancies should be reported IMMEDIATELY and confirmed in writing to the company at the address on the back cover of this manual, or to our appropriate overseas distributor.

4. INSTALLATION

4-4 INITIAL SETTING ANCILIARY EQUIPMENT


- (1) If the machine was delivered in crate, the slideway handles will have been reversed. These should be fitted as illustrated on sketch #35, sketch #36.
- (2) To prepare your machine if delivery is made with the milling head in an upside down position:
 - (a) Lower knee approximately 150mm(6").
 - (b) Slacken the four unit head mounting bolts.
 - (c) Support unit head manually and use a spanner on swivel bolt (fig.b) to wind into upright position.
 - (d) Tighten the four unit head mounting bolts.

NOTE:

For continuous operation in the horizontal plane the head lubrication system must be modified (drawing supplied on request).

To set a milling head square to the table, two methods are available:

- (A) Using a large 90° set square mounted on the table, align faces with square.
- (B) An indicator mounted in the spindle nose travelling in a 115mm(4 1/2") radius. It is important that each axis is set separately and locked.



5. PUTTING INTO SERVICE

CUTTING INFORMATION

5-1 CUTTING SPEED

The cutting speed of milling cutter can be expressed by

$$V = \frac{\pi D n}{1000}$$

where:

V=cutting speed

D=diameter of cutter

n=revolution per minute of the spindle

Cutting speed varies between wide limits which are determined by the material being cut, the material used in the cutter, and other conditions which are determined by the specific operation to be performed. Consider the following whenever they are needed:

- (1) Reducing cutting speed will increase cutter life.
- (2) For roughing operations. use lower cutting speed and higher work feed. In finishing operations, higher cutting speed and lower work feed are recommended.
- (3) Use cutting speed below averaged value in the beginning of an new operation and increase it during the operation.
Refer to Table 1. in the selection of cutting speed.

5. PUTTING INTO SERVICE

5-1A TABLE 1. RECOMMENDED CUTTING SPEED

| Workpiece | | Brinell hardness HB | Cutting speed | | | | |
|----------------------|--------------------------|---------------------|--------------------------------|---------|----------|---------|--|
| Material | High speed steel cutter | | Sintered carbide tipped cutter | | | | |
| | | | m/min | ft/min | m/min | ft/min | |
| Special alloy steel | hard tough annealed | 300-400 | 13-15 | 38-45 | 30-50 | 90-150 | |
| | | 220-300 | 15-23 | 45-70 | 50-75 | 150-225 | |
| | | 180-220 | 23-35 | 70-110 | 75-108 | 225-325 | |
| Low carbon steel | ductile free cutting | 152-197 | 28-46 | 35-140 | 90-130 | 270-400 | |
| | | 150-180 | 35-46 | 110-140 | 108-130 | 325-400 | |
| Cast iron | hard medium soft | 220-300 | 15-23 | 45-70 | 50-75 | 150-225 | |
| | | 180-220 | 23-33 | 70-100 | 75-108 | 225-325 | |
| | | 150-180 | 35-46 | 110-140 | 108-130 | 325-400 | |
| Brasses and bronzes | hard medium free cutting | 150-250 | 21-46 | 64-140 | 63-130 | 190-400 | |
| | | 100-150 | 46-83 | 140-250 | 130-200 | 400-600 | |
| Magnesium and alloys | | | | 116-500 | 350-1500 | | |
| Aluminum and alloys | | | | 66-500 | 200-1500 | | |
| Plastics | | | | 66-500 | 200-1500 | | |

5. PUTTING INTO SERVICE

5-2 FEED SPEED

Feed speed is determined by

$$S = N \times s \times Z$$

where:

S=table feed speed

N=revolution per minute of cutter

s=feed per tooth

Z=NO. of teeth of cutter

The feed per tooth is used in most cases. Table 2 gives suggested values of different types of milling cutters and kinds of work material in general conditions.

5. PUTTING INTO SERVICE

5-2A TABLE 2. RECOMMENDED FEED PER TOOTH FOR CUTTERS

| Cutter | Workpiece | | Feed per tooth(mm) | | | | | | |
|------------------|---------------------|--------------------------|-------------------------------|-------------------------------|-------------------------------|-----------------------|-----------------------------|-----------------------|-------------------------|
| | Material | Brinell hardnes Hb | Face mills | Helical mills | Slotting and side mills | End mills | Form relieved cutters | Circular saws | |
| High speed steel | Special alloys | hard tough annealed | 300-400 220-300 180-220 | 0.1 0.13 0.2 | 0.075 0.125 0.175 | 0.075 0.1 0.125 | 0.05 0.075 0.1 | 0.05 0.05 0.025 | 0.025 0.05 0.05 |
| | | ductile free cutting | 152-197 150-180 | 0.25 0.3 | 0.2 0.25 | 0.13 0.175 | 0.125 0.13 | 0.075 0.1 | 0.075 0.035 |
| | | Cast iron | hard medium soft | 200-300 150-250 150-180 | 0.27 0.325 0.4 | 0.2 0.25 0.325 | 0.13 0.175 0.225 | 0.1 0.1 0.125 | 0.075 0.075 0.1 |
| | Brasses and bronzes | hard Medium free cutting | 150-250 100-150 80-100 | 0.225 0.35 0.55 | 0.225 0.35 0.55 | 0.13 0.2 0.325 | 0.125 0.175 0.27 | 0.075 0.1 0.175 | 0.05 0.075 0.125 |
| | | Magnesium and alloys | | 0.55 | 0.45 | 0.325 | 0.27 | 0.175 | 0.125 |
| | | Aluminum and alloys | | 0.55 | 0.45 | 0.325 | 0.27 | 0.175 | 0.125 |
| | plastics | | | 0.375 | 0.3 | 0.225 | 0.175 | 0.125 | 0.1 |
| Sintered carbide | Special alloys | hard tough annealed | 300-400 220-300 180-220 | 0.25 0.3 0.35 | 0.2 0.25 0.27 | 0.13 0.175 0.2 | 0.125 0.13 0.175 | 0.075 0.1 0.1 | 0.075 0.075 0.1 |
| | | ductile free cutting | 152-197 150-180 | 0.35 0.4 | 0.27 0.325 | 0.2 0.225 | 0.175 0.2 | 0.1 0.125 | 0.1 0.1 |
| | | Cast iron | hard medium soft | 220-300 180-220 150-180 | 0.3 0.4 0.5 | 0.25 0.325 0.4 | 0.175 0.25 0.3 | 0.1 0.125 0.13 | 0.075 0.1 0.125 |
| | Brasses and bronzes | hard Medium free cutting | 150-250 160-150 80-100 | 0.25 0.3 0.5 | 0.2 0.25 0.4 | 0.13 0.175 0.3 | 0.125 0.13 0.25 | 0.075 0.1 0.13 | 0.075 0.057 0.125 |
| | | Magnesium and alloys | | 0.5 | 0.4 | 0.3 | 0.25 | 0.13 | 0.125 |
| | | Aluminum and alloys | | 0.5 | 0.3 | 0.3 | 0.25 | 0.13 | 0.125 |
| | plastics | | | 0.572 | 0.3 | 0.225 | 0.175 | 0.125 | 0.1 |

5. PUTTING INTO SERVICE

5-3 CUTTING DEPTH

The following table renders suggested cutting depth of different milling conditions.

Cutting depth of cutter

| Machining type | Cutting depth |
|----------------|---------------|
| finishing | 0.3~0.5 |
| medium | 0.4~1.4 |
| rough | 3~5 |


5. PUTTING INTO SERVICE

5-4 PROBLEM DIAGNOSTIC AND TROUBLESHOOTING OF MILLING

| Problem | Diagnostics | Troubleshooting |
|---|--|--|
| (1) Cutter misalignment during rotation | Misalignment in cutter itself | Properly grinding of cutter and cutting edge |
| | Misalignment while mounting cutter | Reducing clearance between shank and hole |
| | Bending of shank | Grinding the shank properly, reducing tangential forces, and clearing debris |
| (2) Vibration during milling | Workpiece moving up while up milling | Using oblique cutting and down milling |
| | Shank is long and small | Increasing rigidity of shank |
| | Large backlash of leadscrew | Adjusting the backlash |
| | Workpiece is not clamped well | Clamping workpiece firmly |
| | Heavy load in cutting | Reducing spindle speed, cutting depth, and feed rate |
| | The frequency of cutting force variation is close to machine natural frequency | Using cutter with less teeth |
| (3) Loose of End milling cutter | Axial force acts toward the direction away from spindle | Selecting proper oblique and rotational direction to change the direction of axial force |
| (4) Deformation of workpiece | Workpiece is not clamped properly | Change clamping style and do not put excessive clamping force during finishing cutting |
| | Damage on table surface | Smoothing the table surface |
| | residual stress in workpiece | Annealing workpiece thoroughly |
| (5) Discontinuity occurred in plain milling | The center of spindle is not perpendicular to table or saddle | Modifying the sliding way and making it to be perpendicular to spindle |
| | Thermal deformation | Controlling the temperature rising of machine |
| (6) Actual cutting depth does not match the setting value | Shank deforms while milling | Increasing the rigidity of shank and reducing cutting force |
| | Workpiece deformed and was not fixed well | Fixing the workpiece properly |

6. OPERATION

6-1 HEAD CONTROLS




Sketch #8

1. Brake Control.
2. Speed Range Selection Lever.
3. Speed Selection Handwheel.
4. Power Feed Transmission Engagement Lever.
5. Quill Feed Handle.
6. Quill Feed Selector.
7. Quill Feed Control Lever
8. Handwheel for Manual Feed (by hand) of Quill.
9. Quill Feed reversing Knob.
10. Quill Lock
11. Indicator Mounting Rod.
12. Adjustable Micrometer Depth Stop.
13. Quill Stop
14. Quill
15. Draw Bar
16. SPINDLE FOR./REV. SWITCH

6. OPERATION

6-2 OPERATING PANEL




Sketch #9

| | | | |
|---|--------------|---|----------------|
| 1 | SPINDLE ON | 5 | COOLANT ON |
| 2 | SPINDLE STOP | 6 | COOLANT STOP |
| 3 | POWER ON | 7 | PILOT LAMP |
| 4 | POWER STOP | 8 | EMERGENCY STOP |

6. OPERATION

6-3A SWIVEL TURRET


- (a) Use spanner and unlock the 4 bolts.
- (b) Index to the required setting.
- (c) Lock the 4 bolts.



Sketch #10

6-3B MOVE RAM SLIDE

- (a) Use Bridgeport spanner and unlock the two bolts.
- (b) Turn the handle to move the slide to the desired position.
- (c) Lock, tightening the rear bolt first.



Sketch #11


6. OPERATION

6-4A SPINDLE SPEED(Change only when spindle is running)

Change Speed Within Range

- (1) Start spindle.
- (2) Turn handwheel 'A' to select required speed.

Change only when spindle is running.




Sketch #12 DO NOT CHANGE SPEED WHEN SPINDLE IS STATIONARY

6-4B CHANGE RANGE


From direct to back gear drive:

- (1) Switch Sketch #9 ② to OFF.
- (2) Move lever "C" through neutral to LOW (this reverses the spindle rotation).



6-4C FROM BACK GEAR TO DIRECT DRIVE:

- (1) Switch Sketch #9 ② to OFF.
- (2) Move lever "C" through neutral to HIGH
- (3) Rotate spindle by hand until the clutches are felt to engage.




Sketch #13 DO NOT CHANGE RANGE WHEN THE SPINDLE IS RUNNING

6. OPERATION


6-5A SWIVEL BELT HOUSING

- (1) Slacken three Locking Nuts 'A' (Retain sufficiently to stop binding).
- (2) Swivel to required angular setting.
- (3) Tighten three Locking Nuts; before finally securing, run spindle to give correct spline alignment.



NOTE: Incorrect spline alignment can be caused by unequal tightening of the locking nuts 'A' causing varying stiffness of the quill feed which can be felt through the sensitive feed handle.

6-5B SPINDLE BRAKE




BRAKE OFF BRAKE


6-5C QUILL SENSITIVE HAND FEED

Sketch #15

- (1) Place the handle on the boss.
- (2) Select the most suitable position.
- (3) Push home until the locating pin engages.



6. OPERATION



Sketch #17

6-6A FINE HAND FEED

- (1) Disengage Auto Quill Feed 'A'
- (2) Locate 'C' in mid (neutral) position
- (3) Engage Feed Trip Lever 'B'
- (4) The Quill is now under handwheel control.

6-6B AUTOMATIC FEED

Maximum loading 3/8" (9.5mm)
dia. drill in steel


- (1) Ensure quill lock is off 'D'
- (2) Set micrometer dial to required depth 'E'
- (3) Engage auto quill feed 'A' (when motor has stopped).
- (4) Select feed rate 'F'
- (5) Select feed direction 'C'
- (6) Engage feed trip lever "B"
- (7) The feed will automatically trip out at a depth within $\pm 010"$ ($\pm .25\text{mm}$).
- (8) Hand feed to dead stop for repeating accuracy $\pm 001"$ ($\pm 0.25\text{mm}$).

DO NOT ENGAGE QUILL FEED 'A'
OVER 3,000 R.P.M.

6. OPERATION

6-7A CLAMPING THE TABLE SADDLE SLIDE


The table clamping lever is located on front of saddle and should always be clamped when longitudinal movement is not required.(Sketch #18)



Sketch #18

6-7B CLAMPING THE SADDLE KNEE SLIDE

When milling with longitudinal table feed only, it is advisable to clamp the knee to the column and the saddle to the knee to add rigidity to these members and provide for heavier cuts with a minimum of vibration. The saddle locking lever is located on the left-hand side of saddle.(Sketch #19) Excessive pressure can cause slight table. Use moderate clamping pressure, as this will hold saddle sufficiently.




Sketch #19

6. OPERATION

6-7C CLAMPING THE KNEE COLUMN SLIDE

The knee clamping lever is at the left side of the knee and should be drawn downward to clamp the knee. This is only a tension brake and will lock the knee completely. Leave clamped at all times unless using knee in operatin.

IMPORTANT: Two clamps to lock the knee are located on the left side.




Sketch #20

6. OPERATION


6-8A GUARD FOR SAFE USE

We use the spindle safety guard and table guard according to the size of workpiece.

We must adjust the guard for safe use. Operator must use the spindle safety guard and table guard in order to reduce the danger during operation.



Sketch #21 TABLE GUARD NO.1




Sketch #22 SPINDLE SAFETY GUARD

6. OPERATION

6-8B GUARD FOR SAFE USE

We use the spindle safety guard and table guard according to the size of workpiece.

We must adjust the guard for safe use. Operator must use the spindle safety guard and table guard in order to reduce the danger during operation.



Sketch #23


TABLE GUARD NO.2
THE BUYER CAN CHOOSE THE
TABLE GUARD NO.1 OR NO.2

6. OPERATION

6-9 POWER FEED FOR SAFE USE


Before using this machine, you must conform the power feed position (sketch #24) and the exact installation

You have to study the instruction manual of "ALIGN" poewr table feed.



Sketch #24

7. MAINTENANCE



Sketch #25

7-1A TRANSPORTATION

We recommend to fit a rope becket for transporting variable speed head, as shown on Sketch #25

7-1B INSTALLATION

Fit screws Nos. 'A' into the four holes of head.


Then, make a previous tightening by means of four nuts corresponding to screws mentioned above. Finish fastening head with the same nuts.

CAUTION: A bad tightening of nuts could provoke a strain on sensitive parts of head.

7. MAINTENANCE

7-2 MOTOR REMOVAL

- (1) Run head to adjust lowest speed.
- (2) Remove 3 screws 'B' and cover 'A'
- (3) Make a fixture comprised of 'C' 'E' 'F' 'G' 'H'.
- (4) Tighten 2 belts 'C' on pulley "D" and work with fixture. Rotate 'H' clockwise and move spring 'F' up by 10mm.
- (5) Remove C-type retaining ring 'I' and fixture
- (6) Remove pulley 'D' and 4 screws 'M'
- (7) Remove motor 'N'






Sketch #26

7. MAINTENANCE

7-3 COLLECT ALIGNING SCREW REPLACEMENT

- (1) Use felt pen, mark reference line on quill and nose cap 'B'
- (2) Remove set screw 'A'
- (3) Unscrew nose cap 'B'
- (4) Replace nose cap 'B'; check felt pen markings for correct alignment.
- (5) Replace set screw 'A' Caution do not overtighten as this will cause distortion
- (6) Check gap 'E'. (.003=.08mm)





Sketch #27

7. MAINTENANCE

7-3A COLLECT ALIGNING SCREW REPLACEMENT

- (1) Use felt pen, mark reference line on quill and nose cap 'B'.
- (2) Remove set screw 'A'.
- (3) Unscrew nose cap 'B'.
- (4) Remove lock screw 'C' and collet aligning screw
- (5) Replace 'C'; insert R.8 collet and check that the dog on the end of the screw does not foul on the bottom of the guide slot.
- (6) Replace lock screw 'C'
- (7) Replace nose cap 'B'; check felt pen markings for correct alignment.
- (8) Replace set screw 'A'; Caution do not overtighten as this will cause distortion.
- (9) Check gap 'E'





Sketch #28

7. MAINTENANCE

7-4A BALANCE SPRING REPLACEMENT


- (1) With quill at top of movement apply quill lock.
- (2) Remove screw 'A', hub 'B', and key 'C'
- (3) Remove screws 'D', allowing housing to rotate slowly releasing spring tension.
- (4) Lift end of spring from peg on the pinion shaft.
- (5) Rotate housing 'E' anti-clockwise from head casting.
- (6) Remove spring from housing and replace.
- (7) Refit spring to main housing casting, turning housing clockwise until spring locates no peg in pinion shaft.



Sketch #29

7-4B FEED TRIP ADJUSTMENT

- (1) Release locknut 'A'
- (2) Engage trip handle 'C'
- (3) Adjust micro nuts against quill stop 'B'
- (4) Slowly turn adjusting screw 'D' until lever 'C' trips.
- (5) At this point secure locknut 'A'
- (6) Check that smart trip action is obtained.




Sketch #30

7. MAINTENANCE

7-5 QUILL REMOVAL

- (1) Remove screw 'D' and ball reverse lever 'E'.
- (2) Remove circlip 'F', screw 'G' and arm 'H'
- (3) Thread shaft 'J' through micro nuts and remove.
- (4) Remove screw 'K' and stop 'L'.
- (5) Remove quill.
- (6) Clean all areas, oil liberally and reassemble.
- (7) Check correct operation of feed trip linkage. See instruction on sketch #30

Re-assembly of spline alignment. see sketch #31.




Sketch #31

7. MAINTENANCE

7-6A ADJUSTMENT OF TABLE GIB


The table is provided with a full length tapered gib in the saddle, with an adjusting screw on the double side. To take up gib, tighten large screw slightly and repeat until a slight drag is felt when moving the table by hand.



Sketch #32

7-6B ADJUSTMENT OF SADDLE GIB

A tapered gib is used for adjusting the saddle smooth on the knee. This forms a guide for the saddle. To tighten gib same principal as described above is used; however, chip wiper has to be removed first.




Sketch #33

7. MAINTENANCE

7-7 ADJUSTMENT OF KNEE GIB

Remove chip wiper and adjust screw until smooth movement is attained.




Sketch #34

7. MAINTENANCE

7-8 BACKLASH ADJUSTMENT

1. Crank the table to the left.
2. Withdraw screw 'A' 1/2 a turn.
3. Tighten screw 'B' whilst slowly turning handle 'C' until 0.1mm or 0.125mm is obtained.
4. Finally lock screw 'A' on to 'B'.




Sketch #35

7. MAINTENANCE

7-9 BACKLASH ADJUSTMENT


1. Crank the saddle to Mid position.
2. Withdraw 3 screws 'D'
3. Pull the saddle forward to expose screws 'A' & 'B'.
4. Withdraw screw 'A', 1/2 a turn.
5. Whilst slowly turning handle 'C' tighten screw 'B' until 0.1mm or 0.125mm is obtained.
6. Lock screw 'A' onto 'B'
7. Finally crank the saddle to the front of the knee and replace 3 screws 'D'.



Sketch #36

8. LUBRICATION

8-1 VARIABLE SPEED DRIVE HEAD



4 Remove grub screw, screw in tube and squeeze in required amount.

Sketch #37

| FREQUENCY | LUBRICATE | LUBRICANT | QUANTITY | LUB. AT |
|-------------|---------------------------------|-----------|------------|---------|
| Twice Daily | Quill Down Feed | Light Oil | 5-10 Drops | 2 |
| Once Daily | Bearing Block For Hi/Low Change | Light Oil | 5-10 Drops | 3 |

Failure to lubricate at 2 can result in tight quill and partial seizure of quill in housing.

| FREQUENCY | LUBRICATE | LUBRICANT | QUANTITY | LUB. AT |
|----------------|-----------------------------|-----------|-----------------|---------|
| Every 3 Months | Hi-Low Speed Gear Mechanism | Grease | Suitable Amount | 1 , 4 |

8. LUBRICATION

8-2 AUTO OIL-FEED ADJUSTMENT

HIGH


Instructions

1. Fill clean lubricant into the oil tank up to the top red line. Refill oil when the oil surface is below the bottom red line.
2. Pull open the oil feeding button to fill up the pipe.
3. Let the oil feeding button return to its original position by itself. Don't push it back.
4. Be sure to notice if the motor is running properly.
5. If any impurities remain in the oil tank. Please clean it at once and clean the oil absorbing net as well.

The adjustment of flow

Release the fixing bolt, adjust the movable part to the numbers indicating the amount of flow on the non-movable part. Tighten the fixing bolt at the desired flow amount.



LOW



Sketch #38

8. LUBRICATION



8-3 UP-DOWN OIL SYSTEM



Sketch #39

8. LUBRICATION

8-4 SADDLE OIL SYSTEM



Sketch #40

8. LUBRICATION

8-5A COOLANT OIL

| BRAND | SHELL | MOBIL | ESSO | B P | CASTROL |
|-----------|---------------|--------------|---------------|--------------------------|------------------|
| MODEL NO. | DROMUS BS & D | MOBILMET 220 | KATWALL EP-66 | CUTORA M2 & DIATSOL T-50 | CLEAREDGE EP-284 |

8-5B SLIDE WAY OIL

| BRAND | SHELL | MOBIL | ESSO | B P | CASTROL |
|-----------|------------|----------|------------|---------------|-------------|
| MODEL NO. | TONNA T-68 | VACTRA 2 | FEBIS K-68 | MACCURAT D-68 | MAGNA BD-68 |

9. INSTRUCTION FOR DIAGRAM

A. CAUTION

DO NOT TURN
UNLESS
MOTOR IS ROTATING

B. DISENGAGE FEED GEAR

WHEN NOT IN USE
STOP MACHINE BEFORE

C. ← BRAKE →

D. SPEED SELECTION

HI N LO

9. INSTRUCTION FOR DIAGRAM

E.


CAUTION:



DO NOT CHANGE LEVERS.
WHILE THE SPINDLE IS
RUNNING

F. VARIABLE SPEED LIST

The high speed (2560–3600 rpm) is marked red color.
we must be careful to high speed operation.



9. INSTRUCTION FOR DIAGRAM


G. LIST OF RECOMMENDED OILS OR EQUAL

MOBIL VACTRA OIL NO. 2
SHELL TONNA OIL T68

H. PLEASE


ADD
LUBRICANT
BEFORE
USE

I. MACHINE NAMEPLATE





9. INSTRUCTION FOR DIAGRAM

J.



9. INSTRUCTION FOR DIAGRAM

K. GENERAL DIAGRAM POSITION




ANNEX A. PART DRAWING PARTS NAME & NUMBER

| PART NO | DESCRIPTION | QTY | PART NO | DESCRIPTION | QTY | PART NO | DESCRIPTION | QTY |
|---------|--------------------------------|-----|---------|--------------------------------|-----|---------|------------------------------|-----|
| 210 | GEAR | 1 | 771 | WORM GEAR | 1 | 876 | SCREW | 4 |
| 213 | TIMING BELT PULLEY | 1 | 772 | GEAR | 1 | 877 | RING | 1 |
| 231 | BRAKE LOCK HANDLE | 1 | 773 | BUSHING | 2 | 879 | SET SCREW | 1 |
| 232 | BOLT | 1 | 775 | BUSHING | 1 | 880 | PLASTIC BALL | 2 |
| 236 | KEY | 1 | 776 | SPEED OPERATING SHAFT | 1 | 881 | PIN | 1 |
| 456 | PIN | 1 | 777 | BUSHING | 1 | 882 | SCREW | 2 |
| 467 | DRAWBAR WASHER | 1 | 779 | ADJUSTING SCREW (R. T.) | 1 | 883 | SET SCREW | 1 |
| 503 | TIMING BELT 225L | 1 | 781 | ADJUSTING SCREW (L. T.) | 2 | 884 | PIN | 1 |
| 701-1 | ALUMINUM CASE | 1 | 782 | REGULATING NUT | 1 | 885 | NUT | 1 |
| 702-1 | GEAR BOX | 1 | 783 | CHAIN | 1 | 887 | PIN | 1 |
| 703 | MAIN SPINDLE FIXED PULLEY | 1 | 784 | SPEED ADJUST SCREW | 1 | 888 | SCREW | 4 |
| 704 | SUPPORT PLATE | 1 | 786 | NAME PLATE | 1 | 889 | SET SCREW | 2 |
| 705-1A | DOWN COVER | 1 | 787 | HANDWHEEL | 1 | 890 | SCREW | 3 |
| 706-A | PULLEY SHAFT CLUTCH | 1 | 789 | HANDLE | 1 | 891 | WASHER | 1 |
| 707 | MAIN SPINDLE FIXED PULLEY | 1 | 790 | OPERATING SHAFT | 1 | 893 | SCREW | 2 |
| 708 | MAIN SPINDLE SLIDING PULLEY | 1 | 791 | SPEED PLATE | 1 | 894 | KEY | 1 |
| 709 | MOTOR SLIDING PULLEY | 1 | 792 | SPEED DISK | 1 | 896 | MOTOR FIXED PULLEY SET SCREW | 1 |
| 710 | MOTOR FIXED PULLEY | 1 | 825 | BEARING 6007ZZ | 1 | 897 | OIL CUP | 1 |
| 711 | SPINDLE SLIDING PULLEY BUSHING | 2 | 826 | BEARING 6210ZZ | 2 | 898 | OIL NOZZLE | 1 |
| 712 | MOTOR SLIDING PULLEY BUSHING | 2 | 827 | BEARING 6908ZZ | 2 | 899 | BEARING 6204ZZ | 1 |
| 713 | MOTOR PULLEY KEY | 1 | 828 | BEARING 6203ZZ | 2 | | | |
| 715 | SPINDLE BRAKE | 1 | 830 | VARIABLE SPEED BELT 875VC 3830 | 1 | | | |
| 718 | BALANCE BEAM | 1 | 831 | PIN | 1 | | | |
| 720 | TRACTION SPRINGS | 1 | 832 | SCREW | 12 | | | |
| 721 | SLEVE | 1 | 833 | SCREW | 2 | | | |
| 723 | BEARING COVER | 1 | 834 | SCREW | 3 | | | |
| 724 | CLUTCH SLEVE | 1 | 835 | RING | 1 | | | |
| 725 | TOP COVER | 1 | 836 | WAVE WASHER | 1 | | | |
| 726 | BRAKE SHAFT | 1 | 837 | SPRING WASHER | 1 | | | |
| 727 | BRAKE CAMS | 2 | 838 | NUT | 1 | | | |
| 729 | BRAKE SUPPORTER | 1 | 841 | NUT | 1 | | | |
| 731 | BRAKE SHAFT SLEVE | 1 | 842 | PIN | 1 | | | |
| 732 | DRAWBAR | 1 | 843 | MOTOR FIXED PULLEY KEY | 1 | | | |
| 740 | THREE-ADMISSION CLUTCH | 1 | 844 | SCREW | 2 | | | |
| 741 | SLIDING BEARING BOX | 1 | 845 | SCREW | 4 | | | |
| 742 | SPACER(SMALL) | 1 | 847 | SCREW | 3 | | | |
| 743 | SPACER(LARGE) | 1 | 849 | RING | 1 | | | |
| 744 | HIGH-LOW SPEED HUB | 1 | 850 | SPRING WASHER | 3 | | | |
| 745 | TOOTH CHANGE SHAFT | 1 | 851 | NUT | 3 | | | |
| 746 | ROTATION PLATE | 1 | 852 | RING | 1 | | | |
| 747 | LOCKING NOZZLE | 1 | 853 | SCREW | 4 | | | |
| 748 | HIGH-LOW SPEED LEVER | 1 | 854 | PIN | 1 | | | |
| 749 | SPRING | 1 | 857 | SPINDLE FIXED PULLEY KEY | 1 | | | |
| 750 | SPRING | 3 | 858 | WAVE WASHER | 1 | | | |
| 752 | DRIVE RING | 1 | 859 | NUT | 1 | | | |
| 753 | SCREW | 3 | 860 | SPRING WASHER | 1 | | | |
| 755 | DRIVE RING | 1 | 861 | SCREW | 3 | | | |
| 756 | SCREW | 3 | 862 | SET SCREW | 1 | | | |
| 757 | BEARING COVER | 1 | 863 | KET | 1 | | | |
| 758 | GEAR SHAFT | 1 | 865 | SET SCREW | 1 | | | |
| 759 | LOCKING SHAFT | 1 | 866 | PIN | 1 | | | |
| 760 | MAIN MOTOR | 1 | 869 | SET SCREW | 1 | | | |
| 762 | SPRING REST | 1 | 870 | SCREW | 3 | | | |
| 763 | OPERATING SCREW | 1 | 873 | SET SCREW | 1 | | | |
| 764 | LOCKING NUT | 1 | 874 | RING | 1 | | | |
| 770-1 | SPEED CHANGE BOX | 1 | 875 | PIN | 4 | | | |

A. PART DRAWING

A1. VARIABLE HEAD DRAWING




ANNEX A. PART DRAWING PARTS NAME & NUMBER

| PART NO | DESCRIPTION | QTY | PART NO | DESCRIPTION | QTY | PART NO | DESCRIPTION | QTY |
|---------|----------------------------|-----|---------|--------------------------------|-----|---------|-------------------------------|-----|
| J-01 | QUILL HOUSING | 1 | J-107 | KEY | 1 | J-264 | CAP SCREW | 3 |
| J-09 | FEED GEAR CRADLE | 1 | J-108 | DRIVE SHAFT BUSHING | 1 | J-265 | CAP SCREW | 1 |
| J-10 | OVERLOAD CLUTCH TRIP LEVER | 1 | J-109 | SPACER | 1 | J-266 | ROLL PIN | 1 |
| J-11 | FEED GEAR SHIFTER FORK | 1 | J-110 | FEED REVERSE BEVEL GEAR | 2 | J-268 | SOCKET SET SCREW | 1 |
| J-14 | SHIFT CRANK | 1 | J-111 | BEVEL GEAR WASHER | 1 | J-269 | NUT | 1 |
| J-15 | CLUSTER GEAR BOX | 1 | J-112 | FEED REVERSE CLUTCH | 1 | J-272 | LOCK NUT | 1 |
| J-16 | SPRING COVER | 1 | J-113 | SCREW | 1 | J-273 | LOCK MASHER | 1 |
| J-17 | FEED TRIP BRACKET | 1 | J-114 | FEED WORM SHAFT BUSHING | 1 | J-275 | 1/4"-20NC X 1/4" L SOCKET | 1 |
| J-18 | CLUTCH ARM COVER | 1 | J-116 | REVERSE CLUTCH ROD | 1 | J-278 | SET SCREW | 1 |
| J-19 | KEY | 1 | J-117 | REVERSE KNOB | 1 | J-279 | SOCKET SET SCREW | 1 |
| J-21 | HANDWHEEL | 1 | J-118 | HANDWHEEL CLUTCH | 1 | J-280 | ROLL PIN | 1 |
| J-24 | MICRO SCREW JAM NUT | 2 | J-121 | WORM SHAFT KEY | 2 | J-281 | PIN ϕ 5 X 12 L | 1 |
| J-32 | DRAWBAR KNOB | 1 | J-122 | KEY | 4 | J-282 | PIN | 1 |
| J-35 | QUILL SKIRT | 1 | J-123 | BEVEL PINION WASHER | 1 | J-283 | COMPRESSIVE SPRING | 1 |
| J-36 | QUILL STOP KNOB | 1 | J-124 | FEED WORM GEAR SHAFT SLEEVE | 1 | J-284 | PLASTIC BALL 1/4"-20NC | 3 |
| J-37 | QUILL STOP MICRO SCREW | 1 | J-125 | WORM GEAR SPACER | 1 | J-285 | 5/32"-32NC X 5/8" L HD. SCREW | 3 |
| J-38 | MICROMETER NUT | 1 | J-126 | FEED DRIVE WORM GEAR | 1 | J-287 | KEY | 1 |
| J-39 | REVERSE TRIP BALL LEVER | 1 | J-127 | FEED DRIVE WORM GEAR SHAFT | 1 | J-288 | KOHINOR SNAP RING | 1 |
| J-40 | FEED REVERSE TRIP PLUNGER | 1 | J-128 | FEED ENGAGE PIN | 1 | J-289 | QUILL HANDLE LOCK NUT | 3 |
| J-41 | SET SCREW | 1 | J-129 | WORM GEAR CRADLE THROW OUT | 1 | J-303 | NEEDLE BEARING | 1 |
| J-42 | FEED TRIP LEVER | 1 | J-130 | SHIFT SLEEVE | 1 | J-305 | FEED WORM SHAFT BUSHING | 1 |
| J-43 | FEED TRIP PLUNGER | 1 | J-135 | CLUSTER GEAR KEY | 1 | J-307 | WORM | 1 |
| J-44 | TRIP PLUNGER BUSHING | 1 | J-136 | WORM CRADLE BUSHING | 1 | J-308 | PIN | 1 |
| J-45 | TRIP PLUNGER | 1 | J-138 | PIN | 1 | J-309 | PIN | 1 |
| J-46 | FEED TRIP PLUNGER BUSHING | 1 | J-139 | COLLET ALIGNING SCREW | 1 | J-310 | STEEL BALL | 2 |
| J-47 | CAM ROD SLEEVE ASSEMBLY | 1 | J-140 | WORM GEAR | 1 | J-312 | SET SCREW | 1 |
| J-48 | CAM ROD | 1 | J-141 | NUT | 1 | J-313 | SCREW | 1 |
| J-49 | TRIP HANDLE | 1 | J-142 | KEY | 1 | J-319 | SNAP RING | 1 |
| J-51 | OVERLOAD CLUTCH LEVER | 1 | J-143 | 1/4"-20NC X 3/8" L SOCKET SET | 1 | J-321 | SAFETY CLUTCH SPRING | 1 |
| | SPRING PLUNGER | | | SCREW | | J-324 | FEED REVERSE BEVEL GEAR | 1 |
| J-52 | OVERLOAD CLUTCH WASHER | 1 | J-145 | FEED SHIFT ROD | 1 | J-327 | STEEL PINION | 1 |
| J-53 | CLUTCH RING | 1 | J-146 | FEED REVERSE BEVEL GEAR | 1 | J-328 | CLOCK SPRING | 1 |
| J-54 | OVERLOAD CLUTCH SLEEVE | 1 | | PINION | 1 | J-330 | COMPRESSION SPRING | 2 |
| J-57 | OVERLOAD CLUTCH SLEEVE KEY | 1 | J-147 | SLEEVE | 1 | J-331 | KOHINOOR SNAP RING | 1 |
| J-58 | OVERLOAD CLUTCH | 1 | J-148 | PINION SHAFT HUB SCREW | 1 | J-333 | BLACK PLASTIC BALL HANDLES | 1 |
| J-59 | OVERLOAD CLUTCH RING | 1 | J-151 | TRIP LEVEL PIN | 1 | J-336 | SNAP RING | 1 |
| J-60 | OVERLOAD CLUTCH WORM GEAR | 1 | J-154 | CLUTCH RING PIN | 2 | J-346 | SPINDLE BEARING "FAFANTR" | |
| J-61 | PINION SHAFT WORM GEAR | 1 | J-155 | 1/2" T-BOLT | 4 | | "2MM207WIDUL" | 2 |
| | SPACER | | J-156 | FEED REVERSE KNOB STUD | 1 | J-349 | BEARING FAG 6206ZZ | 1 |
| J-62 | QUILL PINION SHAFT BUSHING | 1 | J-157 | QUILL MICRO STOP NUT | 1 | J-350 | SCREW | 4 |
| J-63 | QUILL PINION SHAFT | 1 | J-163 | SET SCREW | 1 | J-351 | SCREW | 1 |
| J-65 | QUILL LOCK SLEEVE | 1 | J-166 | SPINDLE | 1 | J-352 | DOWEL PINS | 1 |
| J-66 | QUILL LOCK SLEEVE | 1 | J-167 | QUILL(SERIAL AND UP) | 1 | J-355 | HEX NUT | 4 |
| J-67 | QUILL LOCK BOLT | 1 | J-169 | SPINDLE DIRT SHIELD | 1 | J-356 | NUT | 1 |
| J-70 | SCREW | 3 | J-170 | BEARING SPACER LARGE FROM | 1 | J-369 | SHAFT | 1 |
| J-71 | SPRING WASHER | 3 | J-171 | BEARING SPACER (SMALL) | 1 | J-373 | SPRING | 1 |
| J-94 | LOWER CLAMPING BOLT SPACER | 2 | J-172 | NOSEPIECE | 1 | M33 | PINION SHAFT HUB SLEEVE | 1 |
| J-97 | GEAR SHIFT PLUNGER | 2 | J-176 | SLEEVE FROM SER. | 1 | M43 | HANDWHEEL HANDLE | 1 |
| J-98 | CLUSTER GEAR SHIFT CRANK | 1 | J-192 | WHSHER | 1 | M47 | LOCK HANDLE | 1 |
| J-99 | FEED DRIVE CLUSTER GEAR | 1 | J-250 | SOCKET SET SCREW | 4 | M51 | INDICATOR ROD SCREW | 1 |
| J-100 | FEED DRIVE CLUSTER GEAR | 1 | J-251 | SOCKET SET CAP SCREW | 1 | M52 | INDICATOR ROD | 1 |
| J-101 | FEED DRIVE CLUSTER GEAR | 1 | J-255 | R. HEAD SCREW | 3 | M53 | PINION SHAFT HUB | 1 |
| J-102 | SET PIN | 1 | J-256 | COMPRESSION SPRING | 1 | M54 | PINION SHAFT HUB HANDLE | 1 |
| J-103 | FEED DRIVE GEAR | 1 | J-260 | 3/16"-24NC X 1/2" L DOWEL PING | 2 | M72 | WASHER | 4 |
| J-104 | DRIVE GEAR SHAFT | 1 | J-261 | ROLL PIN | 2 | M89 | CLOCK SPRING STUD | 1 |
| J-106 | CLUSTER GEAR SHAFT | 1 | J-262 | COMPRESSIVE SPRING | 2 | F61 | OVERLOAD CLUTCH LOCKNUT | 1 |
| | | | J-263 | SET SCREW | 1 | | | |

A. PAKI DRAWING

A2. VERTICAL MILLING HEAD DRAWING




ANNEX A. PART DRAWING PARTS NAME & NUMBER

| PART NO | DESCRIPTION | QTY | PART NO | DESCRIPTION | QTY |
|----------------|--|-----|---------|-----------------------|-----|
| H-28 | HANDLE | 1 | H-239 | SET SCREW | 1 |
| H-50 | KNEE | 1 | H-240 | ADAPTER LOCKING BOLT | 3 |
| H-59 | BEVEL GEAR | 1 | H-243 | 3/8"-16NC BALL | 1 |
| H-60 | BEVEL PINION | 1 | H-254 | TURRET | 1 |
| H-61 | WOODRUFF KEY | 4 | H-256 | SPIDER | 1 |
| H-62 | 6204ZZ GREASE-SEALED BALL BEARINGS | 3 | H-270 | TURRET CLAMP BOLTS | 4 |
| H-63 | GEAR SHAFT | 1 | H-271 | COLUMN | 1 |
| H-64 | BEARING CUP | 1 | H-272 | WASHER | 4 |
| H-65 | BEARING RETAINER RING | 3 | H-273 | RAM GIB SET SCREW | 2 |
| H-66 | 1/4"-20NC X 3/4" L HOLLOW HEAD CAP SCREW | 9 | H-274 | SCALE | 1 |
| H-67 | DIAL WITH 100 GRADUATIONS | 1 | H-275 | RIVET | 16 |
| H-68 | DIAL HOLDER | 1 | H-276 | REFERENCE POINT PLATE | 1 |
| H-69 | DIAL WITH NUT | 3 | H-278 | REFERENCE POINT PLATE | 1 |
| H-70 | GEARSHAFT CLUTCH INSERT | 1 | H-279 | REFERENCE POINT PLATE | 3 |
| H-71 | ELEVATING CRANK | 1 | H-280 | RUBBER PLUNGER | 6 |
| H-72 | WASHER | 3 | H-281 | SET SCREW | 1 |
| H-76 | 6204Z GREASE-SEALED BALL BEARINGS | 2 | H-237 | RAM PINION HANDLE | 1 |
| H-78 | DIA WITH 200 GRADUATINOS | 2 | | | |
| H-079 | DIAL HOLDER | 2 | | | |
| H-80 | BALL CRANK HANDLE | 2 | | | |
| H-81 | 1/2"-20NF JAM NUT | 2 | | | |
| H-82 | 3/8"-16NC X 1" L HOLLOW HEAR CAP SCREW | 8 | | | |
| H-87 | KNEE COLUMN GIB | 1 | | | |
| H-088 | ADJUSTING SCREW | 3 | | | |
| H-088-1 | SET SCREW | 3 | | | |
| H-93+H-94+H-95 | ELEVATING LOCK | 2 | | | |
| H-097 | ALUMINUM PLATE | 4 | | | |
| H-099 | FELT WIPER | 1 | | | |
| H-102 | PIN | 4 | | | |
| H-105 | SADDLE | 1 | | | |
| H-110 | FEED NUT BRACKET | 1 | | | |
| H-112 | LONGITUDINAL FEED NUT | 1 | | | |
| H-113 | LONGITUDINAL FEED SCREW | 1 | | | |
| H-114 | TABLE | 1 | | | |
| H-115 | LEFT BEARING BRACKET | 1 | | | |
| H-116 | LONGITUDINAL LEADScrew ADJUSTING NUT | 1 | | | |
| H-117 | SCREW | 4 | | | |
| H-118 | RIGHT BEARING BRACKET | 1 | | | |
| H-119 | SADDLE TABLE GIB | 1 | | | |
| H-120 | TABLE LOCK PLUNGER | 3 | | | |
| H-121 | TABLE LOCK BOLT | 3 | | | |
| H-122 | TABLE LOCK BOLT HANDLE | 2 | | | |
| H-123 | TABLE STOP BRACKET | 1 | | | |
| H-124 | 8 X 20L HOLLOW HEAD CAP SCREW | 2 | | | |
| H-129 | SADDLE KNEE WIPER PLATE | 2 | | | |
| H-130 | FELT WIPER | 2 | | | |
| H-131 | SADDLE KNEE GIB | 1 | | | |
| H-132 | SADDLE LOCK PLUNGER | 1 | | | |
| H-136 | 8 X 20L OVER HEAD SCREW | 10 | | | |
| H-224 | RAM | 1 | | | |
| H-225 | RAM ADAPTER | 1 | | | |
| H-228 | ADAPTER PIVOT STUD | 1 | | | |
| H-229 | ADAPTER PIVOT STUD LOCKNUT | 1 | | | |
| H-230 | OVERARM GIB | 1 | | | |
| H-231 | RAM PINION | 1 | | | |
| H-236 | ANGLE PLATE | 1 | | | |

A. PAKI DRAWING

A3. LEFT-RIGHT DRAWINGS, UP-DOWN DRAWING




ANNEX A. PART DRAWING PARTS NAME & NUMBER

| PART NO | DESCRIPTION | QTY | PART NO | DESCRIPTION | QTY |
|------------------|--|-----|---------|------------------------------|-----|
| H-02 | ELEVATING SCREW HOUSING | 1 | H-271 | COLUMN | 11 |
| H-03 | ELEVATING SCREW NUT | 1 | H-275 | RIVET | 6 |
| H-04 | 8×35L HOLLOW HEAD CAP SCREW | 2 | H-279 | REFERENCE POINT PLATE | 1 |
| H-05 | 1/4"-20NC×5/8"L HOLLOW HEAD CAP SCREW | 3 | H-281 | SET SCREW | 1 |
| H-06 | DOOR | 1 | H-282 | SCREW | 2 |
| H-07 | 6×16L HOLLOW HEAD CAP SCREW | 1 | H-283 | PIN | 2 |
| H-08 | SCREW | 2 | H-284 | PIN | 1 |
| H-09 | PIN | 2 | H-285 | HOISTING RING | 1 |
| H-012 | WOODEN SKID | 1 | H-286 | OIL NETWORK | 2 |
| H-50 | KNEE | 1 | H-287 | CONNECTION PIPE | 4 |
| H-51 | ELEVATING SCREW | 1 | H-288 | 90° TUBE | 2 |
| H-52 | 6305Z CREASE-SEALED BALL BEARING | 2 | H-289 | HOSE | 1 |
| H-53 | BEARING RETAINER RING | 1 | H-290 | COLLANT PUMP | 1 |
| H-54 | 1/4"-20NC×5/8"L HOLLOW HEAD CAP SCREW | 3 | H-291 | TUBE CLAMP | 1 |
| H-56 | KEY | 1 | H-292 | PIPE TUBE | 1 |
| H-57 | WASHER | 1 | H-293 | CLIPER | 1 |
| H-59 | BEVEL GEAR | 1 | H-294 | VALVE | 1 |
| H-61 | WOODRUFF KEY | 1 | H-295 | COOLANT NOZZLE | 1 |
| H-65 | BEARING RETAINER RING | 1 | H-296 | FIXED HOLDER OF COLLANT PUMP | 1 |
| H-66 | 1/4"-24NC×3/4"L HOLLOW HEAD CAP SCREW | 3 | H-297 | SCREW | 2 |
| H-069 | DIAL HOLDER | 1 | H-298 | NUT | 2 |
| H-75 | CROSS FEED SCREW | 1 | H-299 | SCREW | 2 |
| H-76 | 6204Z GREASE-SEALED BALL BEARINGS | 2 | J-144 | GEAR | 1 |
| H-77 | CROSS FEED BEARING BRACKET | 1 | | | |
| H-78 | DIA WITH 200 GRADUATIONS | 1 | | | |
| H-79 | DIAL HOLDER | 1 | | | |
| H-80 | BALL CRANK HANDLE | 1 | | | |
| H-81 | 1/2"-20NF JAM NUT | 2 | | | |
| H-82 | 3/8"-16NC×1"L HOLLOW HEAR CAP SCREW | 4 | | | |
| H-98 | 3/16"-24NC×1/2"L HOLLOW HEAD CAP SCREW | 4 | | | |
| H-101 | CROSS LEADSCREW FIXED NUT | 1 | | | |
| H-102 | PIN | 4 | | | |
| H-103 | 3/8×1)L STOP SCREW | 1 | | | |
| H-105 | SADDLE | 1 | | | |
| H-106 | CROSS FEED NUT | 1 | | | |
| H-110 | FEED NUT BRACKET | 1 | | | |
| H-111 | 8×25L HOLLOW HEAD CAP SCREW | 4 | | | |
| H-114 | TABLE | 1 | | | |
| H-117 | SCREW | 4 | | | |
| H-119 | RIGHT BEARING BRACKET | 1 | | | |
| H-125 | TABLE STOP PIECE | 2 | | | |
| H-126 | STOP PIECE T-BOLT | 2 | | | |
| H-127 | WASHER | 2 | | | |
| H-128 | 3/8-16NC HEXAGON NUT | 2 | | | |
| H-136 | 8×20L OVAL HEAD SCREW | 2 | | | |
| H-224 | RAM | 1 | | | |
| H-225 | RAM ADAPTER | 1 | | | |
| H-226 | VERTICAL ADJUSTING WORM | 1 | | | |
| H-227 | VERTICAL ADJUSTING WORM SHAFT | 1 | | | |
| H-235 | WORM KEY | 1 | | | |
| H-254 | TURRET | 1 | | | |
| H-266+H-268+H269 | CHIP GUARD COVER PLATES FOR 12" KNEE | 1 | | | |

A. FRONT DRAWING



A4. FRONT-REAR DRAWING







CONTROL SYSTEM DIAGRAM

MODEL KR-V2000

| ITEM | DRAWING NO. | PAGE NO. |
|-----------------------------------|-----------------|----------------|
| LIST OF CONTROL SYSTEM DIAGRAMS | KR-V2000-B1-1 | 1 |
| B1. INSTALLATION DWRAWING | KR-V2000-B1-2 | 2 |
| B2. LAY OUT OF CONTROL PANEL | KR-V2000-B2-1 | 3 |
| B3. LAY OUT OF ELECTRICAL CABINET | KR-V2000-B3-1 | 4 |
| B4. CIRCUIT DIAGRAM | KR-V2000-B4-1-5 | 11,12,13,14,15 |
| B5. PARTS LIST | KR-V2000-B5-1-3 | |







KING-RICH KR-V2000 MILLING MACHINE CIRCUIT DIAGRAM

CONTENTS

| Sheet | Description | Reference No. |
|-------|--|---------------|
| B4-1 | Contents-Overview | KR-V2000-B4-1 |
| B4-2 | Basic control circuit 1 | KR-V2000-B4-2 |
| B4-3 | Basic control circuit 2 | KR-V2000-B4-3 |
| B4-4 | X/Y Axes feed control-1 : power feed with DC motor control | KR-V2000-B4-4 |
| B4-5 | X/Y Axes feed control-2 : Gear type table feed control- X axis | KR-V2000-B4-5 |


FUNCTIONS DESCRIPTION


CONSTRUCTION



Basic control circuit 1,2 +Spindle system + X axis system

OPTIONAL REQUIREMENT


- 1 Power feed with DC motor control
- 2. Gear type power table feed control- X axis







POWER FEED
ON



175

Order parts list

To drawing no.:

Order number:

TAB: Engineer:FRANK LEE

Date:10.05.96

| EIC | Cross-ref. | Type reference | Description | Supplier | Qty. |
|-----|------------|----------------|--|----------------|------|
| Q1 | /12.3 | KG32B | selector switch, | KRAUS & NAIMER | 1 |
| F1 | /12.3 | 1KS15 | FUSE, VDE 0110C 660V RL 300V | SCHLEGEL | 1 |
| F11 | /12.3 | 193BSB60 | CURRENT RANGE : 4-6A AUXILIARY CONTACTOR : 1 NO + 1 NC | AB | 1 |
| S1 | /12.3 | T-16EF64D | select switch | YIEN KUANG | 1 |
| M1 | /12.3 | TF-300 | MOTOR, 3.0HP 4POLES 415V 4AMP | TONG FA | 1 |
| X2 | /12.5 | 2Y5 | | | 4 |
| M2 | /12.5 | CW- | COOLANT MOTOR 1/8 HP, 2 POLE, 0.12AMP, RPM 2850/3450 50/60HZ, AC 415V | JOR WEI | 1 |
| F4 | /12.6 | 1KS15 | FUSE, VDE 0110C 660V RL 300V | SCHLEGEL | 1 |
| T1 | /12.6 | SB-DTO | TRANSFORMER, 450VA 50/60HZ, PRI/SEC: 575,440,415,400, 380/0,24,100, 110V | SUN CHUAN | 1 |
| F5 | /12.6 | 1KS15 | FUSE, VDE 0110C 660V RL 300V | SCHLEGEL | 1 |
| F21 | /13.2 | 1KS15 | FUSE, VDE 0110C 660V RL 300V | SCHLEGEL | 1 |
| X1 | /13.2 | 1.25Y4 | | | 8 |
| H1 | /13.2 | PL-22N-1 | FILAMENT BULB 24V , 1.2W LAMP HOLDER BA9S | YIAN KUANG | 1 |
| S1 | /13.3 | MTO | MUSHROOM EMERGENCY STOP BUTTON, IP65 | SCHLEGEL | 1 |

175

Order parts list

To drawing no.:

Order number:

TAB:

Engineer:FRANK LEE

Date:10.05.96

| EIC | Cross-ref. | Type reference | Description | Supplier | Qty. |
|-----|------------|----------------|--|------------|------|
| S22 | /13.3 | YS-F1 | PUSH BUTTON, MAX. DIELECTRIC VOLTAGE WITH STANDARD 600VAC, Max. continuous current 10Amp. | YIAN KUANG | 1 |
| S21 | /13.3 | YS-F1 | PUSH BUTTON, MAX. DIELECTRIC VOLTAGE WITH STANDARD 600VAC, Max. continuous current 10Amp. | YIAN KUANG | 1 |
| K2 | /13.3 | 100A09NKD3 | CONTACTOR, 3 POLE + 1 NO COIL : AC 24V | AB | 1 |
| S8 | /13.4 | YS-F1 | PUSH BUTTON, MAX. DIELECTRIC VOLTAGE WITH STANDARD 600VAC, Max. continuous current 10Amp. | YIAN KUANG | 1 |
| S6 | /13.4 | YS-F1 | PUSH BUTTON, MAX. DIELECTRIC VOLTAGE WITH STANDARD 600VAC, Max. continuous current 10Amp. | YIAN KUANG | 1 |
| K1 | /13.4 | 100A09NKD3 | CONTACTOR, 3 POLE + 1 NO COIL : AC 24V | AB | 1 |
| K1 | /13.4 | 195FA11 | AUXILIARY CONTACTOR : 1 NO + 1NC | AB | 1 |
| F22 | /13.4 | 1KS15 | FUSE, VDE 0110C 660V RL 300V | SCHLEGEL | 1 |
| X1 | /13.5 | 2Y5 | | | 2 |
| S24 | /13.5 | GE22-P/E02 | HALOGEN BULB SWITCH, | EMENINT | 1 |
| S24 | /13.5 | | | | 1 |
| EL1 | /13.5 | GE22-P/E05 | HALOGEN BULB, 24V 70W | EMENINT | 1 |
| X1 | /13.5 | | | | 1 |

175

Order parts list

To drawing no.:

Order number:

TAB: Engineer:FRANK LEE

Date:05.05.96

| EIC | Cross-ref. | Type reference | Description | Supplier | Qty. |
|-----|------------|----------------|--|------------|------|
| F3 | /13.6 | 1KS15 | FUSE, VDE 0110C 660V RL 300V | SCHLEGEL | 1 |
| X2 | /13.7 | 1.25Y4 | | | 2 |
| M4 | /13.7 | LF-18 | Lubrication pump AC110V 50/ 60HZ 2/2.4RPM 4/3.5W | JIN YIN | 1 |
| X3 | /14.4 | 2Y5 | | | 3 |
| S42 | /14.7 | YS-F1 | PUSH BUTTON, MAX. DIELECTRIC VOLTAGE WITH STANDARD 600VAC, Max. continuous current 10Amp. | YIAN KUANG | 1 |
| K42 | /14.7 | 100A09NKD3 | CONTACTOR, 3 POLE + 1 NO COIL : AC 24V | AB | 1 |
| F81 | /15.4 | 1KS15 | FUSE, VDE 0110C 660V RL 300V | SCHLEGEL | 1 |
| F82 | /15.5 | 1KS15 | FUSE, VDE 0110C 660V RL 300V | SCHLEGEL | 1 |

ANNEX C. NOISE TEST

NOISE LEVEL

1. THE NOISE LEVEL UNDER 80 dB(A) IS CHECKED BEFORE THE MACHINES LEAVE OUR COMPANY.
2. LOCATION OF INSPECTION
 - (1) INSPECTION POINT-1 M AWAY FROM THE MACHINE, AND 1.5M HIGHER THAN THE GROUND.
 - (2) SCOPE OF INSPECTION-FRONT BACK, AND BOTH SIDES, FOUR PLACES OF THE MACHINE.